




**ਦਫਤਰ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ,
ਭਵਨ ਤੇ ਮਾਰਗ, ਸ਼ਾਖਾ, ਮਲੇਰਕੋਟਲਾ**

ਵੱਲ ਪ੍ਰਿੰਸੀਪਲ,
ਤਾਰਾ ਕਾਨਵੈਂਟ ਸਕੂਲ,
ਮਲੇਰਕੋਟਲਾ। (Mob- 94659-22018)

ਨੰਬਰ 10 ਮਿਤੀ 11/04/2023
ਵਿਸ਼ਾ: ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਲੈਣ ਸਬੰਧੀ (ਤਾਰਾ ਕਾਨਵੈਂਟ ਸਕੂਲ ਮਲੇਰਕੋਟਲਾ)
ਹਵਾਲਾ: ਆਪ ਜੀ ਦਾ ਪੱਤਰ ਨੰ: TCS/MLK/3739, ਮਿਤੀ 10/04/2023

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਅਤੇ ਹਵਾਲਾ ਅਧੀਨ ਪੱਤਰ ਦੇ ਸਬੰਧ ਵਿੱਚ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਇਸ ਉਪ ਮੰਡਲ ਦਫਤਰ ਦੇ ਜੂਨੀਅਰ ਇੰਜੀਨੀਅਰ ਸ੍ਰੀ ਬਲਪ੍ਰੀਤ ਸਿੰਘ ਵੱਲੋਂ ਆਪ ਜੀ ਦੇ ਸਕੂਲ ਦਾ ਨਿਰੀਖਣ ਕਰਨ ਉਪਰੰਤ ਰਿਪੋਰਟ ਕੀਤੀ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਸਾਲ 2023-24 (31-03-2024) ਤੱਕ ਬਾਹਰੋਂ ਵੇਖਣ ਵਿੱਚ ਸੇਫ ਜਾਪਦੀ ਹੈ। ਇਸ ਤੋਂ ਇਲਾਵਾ ਇਹ ਵੀ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਵਿੱਚੋਂ ਜੇਕਰ ਕੋਈ ਵੀ ਅਡੀਸ਼ਨਲ ਆਲਟਰੇਸ਼ਨ ਕਰਨੀ ਹੈ ਤਾਂ ਕਿਸੇ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈੱਕ ਕਰਵਾ ਕੇ ਤਸਦੀਕ ਕਰਵਾਇਆ ਜਾਵੇ। ਜੇਕਰ ਹੜ੍ਹ, ਕੁਦਰਤੀ ਆਫਤ ਨਾਲ ਕੋਈ ਵੀ ਦੀਵਾਰ, ਨੀਹਾਂ ਬਹਿੰਦੀਆਂ ਹਨ ਤਾਂ ਉਸ ਬਾਰੇ ਵੀ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈੱਕ ਕਰਾਉਣ, ਉਪਰੰਤ ਤਸਦੀਕ ਵੀ ਕਰਵਾਇਆ ਜਾਵੇ। ਇਸ ਦੀ ਇੰਸਪੈਕਸ਼ਨ ਫੀਸ ਜੀ.ਆਰ.ਨੰ: 663555 ਮਿਤੀ: 11/04/2023 ਰਾਹੀਂ 10,000/- ਰੁਪਏ ਜਮ੍ਹਾਂ ਕਰਵਾ ਲਈ ਗਈ ਹੈ। ਇਸ ਦੇ ਨਾਲ ਹੀ ਆਪ ਨੂੰ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਸਕੂਲ ਦਾ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ 13-09-2023 ਨੂੰ ਮਿਆਦ ਖਤਮ ਹੋਣ ਉਪਰੰਤ ਰੀਨਿਊ ਕਰਵਾ ਕੇ ਇਸ ਦਫਤਰ ਜਮ੍ਹਾਂ ਕਰਵਾਉਣਾ ਯਕੀਨੀ ਬਣਾਇਆ ਜਾਵੇ ਜੀ।


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਲੋ:ਨਿ:ਵਿ:
ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਮਲੇਰਕੋਟਲਾ।
17

ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ: ਮਿਤੀ:
ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਮਲੇਰਕੋਟਲਾ ਜੀ ਨੂੰ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਲੋ:ਨਿ:ਵਿ:
ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਮਲੇਰਕੋਟਲਾ।


Building safety report

Name of School:- TARA CONVENT SCHOOL, MALERKOTA.

As per report of Sh. Balpreet Singh (Junior Engineer) on his visually inspection, the above mentioned school seems visually safe subject to the following observations and conditions:-

1. However, the Parameters to check the stability and safety of building such as Architectural Drawings, Bearing capacity, Foundation details, Structural drawings, Technical Specifications, Test reports of Material used and Quality control reports are not available.
2. In case any addition, alteration, expansion and modification to this building are required to be done, regarding this inspection of undersigned may be arranged and obtained a certificate after the completion from the undersigned.
3. In the case of building is affected by flood or if there is any settlement of walls foundation of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.
4. A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
5. A separate certificate regarding Electrical works should be obtained be from the competent Authority.
6. The owner of the building/ Management is fully responsible regarding safety of the building from all angles in spite of this report.
7. This report is for the covered area of the building as per Drawing submitted by the owner.
8. This report is not valid for legal purpose.

As per visually inspection as reported by the concerned Junior Engineer the above building may be used for normal use for One year up to 31/03/2024 subject to the above conditions.


Sub-Divisional Engineer,
Provl. Sub- Division,
PWD B&R Malerkotla.